

7. Install safety locks before transporting, or working beneath components.
8. Do not allow riders at any time.
9. Do not leave machine unattended with engine running.
10. Keep all hydraulic lines, couplings, and fittings free of leaks during operation.
11. Keep away from overhead electrical lines. Electrocuting can occur without direct contact.
12. Review safety instructions periodically.

5. mantenga las manos, pies, o movimiento.
6. Mantenga a otras personas.
7. Instale trabas de seguridad debajo de los componentes.
8. No permita en ningún momento.
9. No deje a la máquina sin operación.
10. Mantenga todas las líneas hídricas durante el funcionamiento.
11. Permanezca alejado de las líneas de electrocución sin contacto.
12. Analice las instrucciones de



EXHIBIT 5

3:18-CV-256